



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, IL 60604-3590

US EPA RECORDS CENTER REGION 5



501409

Via Facsimile

REPLY TO THE ATTENTION OF:

June 22, 1995

Gerald R. Myers, Vice President
Metcalf and Eddy
2800 Corporate Exchange Drive, Suite 250
Columbus, OH 43231

**RE: Transport of Wastes to Envirosafe Facility from
Granville Solvents Superfund Site**


Dear Mr. Myers:

This letter responds to your 6/1/95 letter regarding GSSPRP's proposal for disposal of investigation- and construction-derived waste soils offsite as hazardous waste. EPA finds this proposal acceptable, and provide this verification that Metcalf and Eddy (M&E) is not prohibited from removing, transporting and disposing of the waste soils noted in your 6/1/95 letter from the Granville Solvents Superfund site in Granville Ohio to the Envirosafe licensed hazardous waste disposal facility in Oregon, OH. EPA has verified with Chuck Hill of Ohio EPA that the Envirosafe disposal facility is currently in compliance with applicable regulations. EPA understands that the quantity of soils to be shipped are approximately 150 tons of soils, in approximately 10-15 roll-off containers, and that analytical results indicate low levels of acetone, methylene chloride, TCE, PCE, copper and zinc. EPA understands that the expected schedule for waste shipment is June/July 1995, via truck transportation, roll-off containers.

EPA requests that the following information be provided at least one week prior to shipment in a letter to USEPA, OEPA's Fred Myers, and OEPA's Chuck Hill: a schedule for all activities; assurances that the soil movement activity will not result in releases of soils from the site to the public areas outside the site perimeter and fence, and assurances that manifesting procedures will be followed and will meet all applicable transport regulations.

If you have any questions regarding this letter, please contact me at (312) 353-9228.

Sincerely yours,


Edward J. Hanlon

cc: Mike Anastasio, EPA-ORC
Chuck Hall, OEPA (fax)

Fred Myers, OEPA (fax)
Mike Raimonde, M&E (fax)



Printed on Recycled Paper



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

Cover Letter Via Facsimile

June 22, 1995

Chuck Hall
Ohio EPA - Northwest District Office
347 North Dunbridge Road
Bowling Green, OH 43402

**RE: Transport of Wastes to Envirosafe Facility from
Granville Solvents Superfund Site**

Dear Mr. Hall:

The U.S. Environmental Protection Agency (EPA) is hereby providing notice to OEPA that an off-site shipment of waste materials (investigation and construction derived waste soils) from the Granville Solvents Superfund site in Granville Ohio at the Envirosafe licensed hazardous waste disposal facility in Oregon, OH. This notice is provided pursuant to Superfund policy. Through my telephone confirmation from you yesterday, EPA has verified with Ohio EPA that the Envirosafe facility is currently in compliance with applicable regulations. The following information is provided regarding this planned shipment:

- 1) Name and location of facility to which waste materials are be shipped: Envirosafe licensed hazardous waste disposal facility in Oregon, OH.
- 2) Name and location of facility from which wastes are be shipped: Granville Solvents Superfund site in Granville, Ohio.
- 3) Type and quantity of wastes are to be shipped: approximately 150 tons of soils, in approximately 10-15 roll-off containers (analytical results and cover request letter provided in Enclosure 1, from Mike Raimonde of Metcalf and Eddy (614-890-5501, x281)).
- 4) Expected schedule for waste shipment: June/July 1995.
- 5) Expected method of transportation: Truck transportation, rolloff containers.



Printed on Recycled Paper

EPA has requested that the following information be provided by the Granville Solvents PRPs at least one week prior to shipment in a letter to USEPA, OEPA's Fred Myers, and OEPA's Chuck Hill: a schedule for all activities; assurances that the soil movement activity will not result in releases of soils from the site to the public areas outside the site perimeter and fence, and assurances that manifesting procedures will be followed and will meet all applicable transport regulations.

If you have any questions regarding this planned activity, please contact me at (312) 353-9228, or Mr. Mike Raimonde of Metcalf and Eddy (614-890-5501, x281).

Sincerely,



Edward J. Hanlon

Enclosure

cc: Mike Anastasio, EPA-ORC
Fred Myers, OEPA (cover letter fax)
Gerry Myers, M&E (cover letter fax)
Mike Raimonde, M&E (cover letter fax)

EPA has requested that the following information be provided by the Granville Solvents PRPs at least one week prior to shipment in a letter to USEPA, OEPA's Fred Myers, and OEPA's Chuck Hill: a schedule for all activities; assurances that the soil movement activity will not result in releases of soils from the site to the public areas outside the site perimeter and fence, and assurances that manifesting procedures will be followed and will meet all applicable transport regulations.

If you have any questions regarding this planned activity, please contact me at (312) 353-9228, or Mr. Mike Raimonde of Metcalf and Eddy (614-890-5501, x281).

Sincerely,



Edward J. Hanlon

Enclosure

cc: Mike Anastasio, EPA-ORC
Fred Myers, OEPA (cover letter fax)
Gerry Myers, M&E (cover letter fax)
Mike Raimonde, M&E (cover letter fax)



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

Cover Letter Via Facsimile

June 22, 1995

Chuck Hall
Ohio EPA - Northwest District Office
347 North Dunbridge Road
Bowling Green, OH 43402

**RE: Transport of Wastes to Envirosafe Facility from
Granville Solvents Superfund Site**

Dear Mr. Hall:

The U.S. Environmental Protection Agency (EPA) is hereby providing notice to OEPA that an off-site shipment of waste materials (investigation and construction derived waste soils) from the Granville Solvents Superfund site in Granville Ohio at the Envirosafe licensed hazardous waste disposal facility in Oregon, OH. This notice is provided pursuant to Superfund policy. Through my telephone confirmation from you yesterday, EPA has verified with Ohio EPA that the Envirosafe facility is currently in compliance with applicable regulations. The following information is provided regarding this planned shipment:

- 1) Name and location of facility to which waste materials are be shipped: Envirosafe licensed hazardous waste disposal facility in Oregon, OH.
- 2) Name and location of facility from which wastes are be shipped: Granville Solvents Superfund site in Granville, Ohio.
- 3) Type and quantity of wastes are to be shipped: approximately 150 tons of soils, in approximately 10-15 roll-off containers (analytical results and cover request letter provided in Enclosure 1, from Mike Raimonde of Metcalf and Eddy (614-890-5501, x281).
- 4) Expected schedule for waste shipment: June/July 1995.
- 5) Expected method of transportation: Truck transportation, rolloff containers.

